




User Prompt  What defect is present in the image?

Input Image



GPT-5
(Zero Shot)




The defect is heavy soiling and surface contamination on the solar panel glass, which reduces light transmission and efficiency.

The defect visible here is a cell crack (microcrack) — the dark, jagged line running across the cell indicates a fracture in the silicon.

A likely defect here is snail-trail/microcrack damage — faint whitish lines and discoloration across some cells indicate underlying cell micro-cracks, not shading.

Gemini 2.5 Flash
(Fine-tuned)



Defect Type: Clean Panel
Defect Category Probabilities:
- **Clean Panel:** 80%
- **Short Circuit:** 15%
- **Black Core:** 5%
Most Likely Cause: Panel is defect-free and functioning correctly.
Visual traits observed: Completely black image, no visible defects or irregularities.
Recommendation: No remediation needed. Panel appears to be in good condition.

Defect Type: Crack
Defect Category Probabilities:
- **Crack:** 95%
- **Delamination:** 5%
- **Contamination:** 5%
Most Likely Cause: Mechanical stress during handling or installation, or thermal stress from temperature fluctuations.
Visual traits observed: Thin, dark, linear features traversing multiple cells.
Recommendation: Further inspection is recommended to assess the severity.

Defect Type: Clean Panel
Defect Category Probabilities:
- **Clean Panel:** 95%
- **Finger:** 3%
- **Crack:** 2%
Most Likely Cause: Proper manufacturing and installation, with no external factors causing damage.
Visual traits observed: Uniform surface, no visible cracks, discoloration, or hotspots.
Recommendation: No remediation needed. Continue regular maintenance and monitoring.

Solar Panel Expert



Defect Type: Clean Panel
Confidence: 100%
Alternative Classification:
- Cannot be classified to others
Most Likely Cause: No Defect/Normal Operation
Visual traits observed: The panel surface exhibits diffuse streaks and spots of dust or dirt, creating a hazy pattern. However, no cracks, burns, black cores, or dislocations are present.
Recommendation: No immediate action needed

Defect Type: Crack
Confidence: 80%
Alternative Classification:
- Black Core, Vertical Dislocation, Finger
Most Likely Cause: Mechanical / Thermal Stress
Visual traits observed: Diagonal crack line running continuously across multiple solar cells from upper region downward
Recommendation: Replace the panel

Defect Type: Clean Panel
Confidence: 100%
Alternative Classification:
- Cannot be classified to others
Most Likely Cause: No Defect/Normal Operation
Visual traits observed: Multiple intact modules exhibit a consistent blue-black color with no visible defects
Recommendation: No immediate action needed

REVL-PV



Defect Type: Clean Panel
Defect Category Probabilities:
- **Clean Panel:** 80%
- **Dirt Accumulation:** 15%
- **Surface imperfection:** 5%
Most Likely Cause: Environmental exposure resulting in surface accumulation.
Visual traits observed: Presence of what seems to be dirt/debris across multiple cells.
Recommendation: Regular cleaning of the panel surfaces is recommended.

Defect Type: Crack
Defect Category Probabilities:
- **Crack:** 95%
- **Microcrack:** 3%
- **Snail Track Crack:** 2%
Most Likely Cause: Mechanical stress during handling or thermal stress.
Visual traits observed: A distinctive crack line spanning multiple cells.
Recommendation: Replacement recommended to prevent further performance degradation and potential safety issues.

Defect Type: Clean Panel
Defect Category Probabilities:
- **Clean Panel:** 95%
- **Minor dirt/dust:** 4%
- **Surface imperfection:** 1%
Most Likely Cause: Environmental factors such as dust, pollen, or bird droppings.
Visual traits observed: Pristine surface, clearly defined cells and busbars, minimal visible debris.
Recommendation: Regular cleaning of the panel surfaces is recommended.