



Input Dta & Knoledge Base



Multi-task numerical annotation

Classification labels
Bounding boxes
Segmentation masks ...



Annotation to structured text

VQA Generation Pipeline


Pavement VQA question pool

Classification
Location
Quantification
Severity
Maintenance
...

Metadata JSON

```
{  
  "Question text,  
  structural text,  
  supportive clue"  
}
```

Advanced MLLM



Validation & Dataset Refinement



Pavement Domain
Expert Review &
Verification


Adversarial / Error-
Correction Pair
Generation

Final
VQA dataset



PaveVQA Dataset Preview & Visual Question Types

Single-turn: classification




What's the main direction of the crack?



Horizontal.

Single-turn: quantification




Give a total crack length in pixels.



About 656 pixels.

Single-turn: location




Where is the patch in the image?



On the right side of the image, around x=366-411 spanning from the top to the bottom.

Single-turn: maintenance




Rate the severity and give a brief maintenance recommendation.



A pothole is present on the asphalt ... patch perimeter to prevent water infiltration.

Multi-turn dialogue



Is there any pavement distress here?



Yes, there is an alligator cracking type distress.



What fraction of the image does it cover in type?



About 10% of the image.



Would you mark it minor or severe, and what should we do next for maintenance?



Severe; schedule prompt repair such as full-depth patching or localized reconstruction, then seal and restore the surface.