







(a) $C_I = 0.50$, Attack 10% sensors




(b) $C_I = 0.50$, Attack 20% sensors




(c) $C_I = 0.50$, Attack 30% sensors




(d) $C_I = 0.50$, Attack 50% sensors




(e) $C_I = 1.00$, Attack 10% sensors



(f) $C_I = 1.00$, Attack 20% sensors



(g) $C_I = 1.00$, Attack 30% sensors



(h) $C_I = 1.00$, Attack 50% sensors