
Transmitter
Receiver
Excitation signal $s(t)$
Excitation signal $s(t)$
$e^{j\phi_{a_1}}$
Reflected signal
$r_1(t) = s(t)e^{j2\pi f_s t}\underbrace{e^{j\phi_{\text{full}}}e^{j\phi_{a_1}}}_{\text{Phase Terms}}$
$s(t)$
Signal Plane
Ground Plane
$s(t)e^{j\phi_{\text{full}}}$
f_s
50Ω


Transmitter
Receiver
Excitation signal $s(t)$
Excitation signal $s(t)$
$e^{j\phi_{a_1}}$
Reflected signal
$r_2(t) = s(t)e^{j2\pi f_s t}\underbrace{e^{j\phi_{\text{touch}}}e^{j\phi_{a_1}}}_{\text{Phase Terms}}$
$s(t)$
F
$s(t)e^{j\phi_{\text{touch}}}$
$\phi_{\text{full}} - \phi_{\text{touch}}$ will give
a measure of $L - l_1$
f_s
50Ω