
Central
Hier
SynCron
Ideal
Lock
Speedup
0
1
2
3
4
5
50
100
200
400
1K
2K
5K
Instructions between
critical sections
Barrier
Speedup
0
2
4
6
8
20
50
100
200
500
1K
2K
Instructions between
barrier synchronization
Semaphore
Speedup
0
1
2
3
100
200
400
1K
2K
5K
10K
Instructions between
semaphore synchronization
Condition Variable
Speedup
0
3
6
9
12
15
200
400
1K
2K
5K
10K
50K
Instructions between
condition variable synchronization