



$\nu = 0.4$  $\nu = 0.499$  $\times$ $\tau = 1/16$ $\square$ $\tau = 1/64$ --- $\tau = 1/256$ $\circ$ $\tau = 1/32$ $\star$ $\tau = 1/128$ $\cdots$ $O(N^2 \log(N^2))$