


5% leakage fault in tank 1



dynamic threshold

