

7% plugging fault between tank 1 and tank 2

