




■ P-Q capability sets + initial operating point
• new operating point (flexibility request)



Capacity = 1.0 pu
Cost = 5.0 pu
Surplus = 5.0 pu



= 2.0 pu
= 16.0 pu
= 4.0 pu



= 2.0 pu
= 13.0 pu
= 7.0 pu