

Device verification

(Probabilistic) verification of the device

Static properties

Measure device properties, e.g. the topology and the qubits connectivity

Benchmark metrics

A metric should aim to capture a particular behaviour of the performance of a device, e.g. CLOPS for speed

Transpiler and flags

Select a transpiler and the transpilation flags to be used

Base setup

Define base experiment flags allowed

Peak setup

Define peak experiment flags allowed

Verification protocol

Establish what verification protocol is used to confirm the correctness of the execution of the routines, e.g., through cross-validation against classical simulations when feasible, statistical tests, or other verification methods.

Test suite

Define the family of routines to be executed as part of the benchmark

Execute test suite for base setup

Execute the test suite using the base configuration, and measure the benchmark metrics defined for the benchmark

Execute test suite for peak setup

Execute the test suite using the peak configuration, and measure the benchmark metrics defined for the benchmark

Benchmark report results

Compile all results from the execution of the test suite for the Peak and base configuration. Include the static properties, the verification protocol, and the configuration used for peak and base executions