
Shoe Lacing
Chip Handover
Cucumber Peeling
Vase Wiping
Lock Opening
Wrong Threading Direction
Large Force
Large Force and Slippage
Incorrect Grasp Point
Incorrect Grasp Point
Wrong Handover Position
Peeling Hesitation
Incorrect Contact Point
Incorrect Insertion Point
Shoelace Slippage
Incorrect Insertion Point
Peeling Gap
Large Force
Rotation with Insertion Gap