




[Edit Instruction] Improve diagnostic clarity of the CT by removing metal degradation while ensuring zero change to medically relevant content outside the artifact zone.



[Edit Instruction] Filter out motion artifacts from the PD MRI scan without smoothing, warping, or otherwise altering true tissue signals.




[Edit Instruction] Render the CT with Abdominal window parameters to mimic how it would appear on a PACS viewer configured for that tissue type.




[Edit Instruction] Process the T1 MRI to mitigate motion effects without changing the appearance of brain tissue, tumors, or other clinical features.



[Edit Instruction] Apply post-processing to remove metal artifacts from the CT image without smoothing, interpolating, or altering real anatomical details unnecessarily.



[Edit Instruction] Convert the given T2-MRI image to resemble a CT image, maintaining all underlying medical information intact.



[Edit Instruction] Process the low-dose CT using a SOFT kernel to suppress graininess while preserving low-contrast diagnostic details.