


Target

Erroneous CAD


Error-Corrected CAD



```

sketch0 = []
loop0_0 = Loop()
loop0_0.Line(endpoint=(95, 0))
loop0_0.Line(endpoint=(164, 61))
loop0_0.Line(endpoint=(0, 56))
loop0_0.Line(endpoint=(0, 0))
sketch0.add(loop0_0)
Extrude(sketch=sketch0,
orientation_degrees=(0, 0, 0),
origin=(0, 0, 0), scale=0.62,
extrude_distance=(50, -3),
boolean_type='New',
extent_type='One-sided')
sketch1 = []
loop1_0 = Loop()
loop1_0.Line(endpoint=(35, 0))
loop1_0.Line(endpoint=(35, 95))
loop1_0.Line(endpoint=(0, 134))
loop1_0.Line(endpoint=(0, -1))
sketch1.add(loop1_0)
Extrude(sketch=sketch1,
orientation_degrees=(0, 0, 0),
origin=(0, 0, 58), scale=0.97,
extrude_distance=(32, 0),
boolean_type='Joining',
extent_type='One-sided')



```



```

sketch0 = []
loop0_0 = Loop()
loop0_0.Line(endpoint=(95, 0))
loop0_0.Line(endpoint=(95, 63))
loop0_0.Line(endpoint=(0, 63))
loop0_0.Line(endpoint=(0, 0))
sketch0.add(loop0_0)
Extrude(sketch=sketch0,
orientation_degrees=(0, 0, 0),
origin=(0, 0, 0), scale=0.75,
extrude_distance=(32, 0),
boolean_type='New',
extent_type='One-sided')
sketch1 = []
loop1_0 = Loop()
loop1_0.Line(endpoint=(35, 0))
loop1_0.Line(endpoint=(35, 95))
loop1_0.Line(endpoint=(0, 95))
loop1_0.Line(endpoint=(0, 0))
sketch1.add(loop1_0)
Extrude(sketch=sketch1,
orientation_degrees=(0, 0, 0),
origin=(0, 0, 32), scale=0.49,
extrude_distance=(32, 0),
boolean_type='Joining',
extent_type='One-sided')

```



```

sketch0 = []
loop0_0 = Loop()
loop0_0.Line(endpoint=(108, 0))
loop0_0.Arc(endpoint=(-66, 115),
degrees=90,
counterclockwise=False)
loop0_0.Line(endpoint=(0, 73))
loop0_0.Line(endpoint=(66, 29))
loop0_0.Arc(endpoint=(0, 0),
degrees=180,
counterclockwise=False)
...
sketch2 = []
loop2_0 = Loop()
loop2_0.Arc(endpoint=(0, 107),
degrees=185,
counterclockwise=False)
loop2_0.Line(endpoint=(0, 28))
loop2_0.Line(endpoint=(0, 122))
loop2_0.Arc(endpoint=(0, 0),
degrees=241,
counterclockwise=True)
...

```



```

sketch0 = []
loop0_0 = Loop()
loop0_0.Line(endpoint=(95, 0))
loop0_0.Line(endpoint=(95, 28))
loop0_0.Arc(endpoint=(66, 57),
degrees=90,
counterclockwise=False)
loop0_0.Line(endpoint=(0, 57))
loop0_0.Arc(endpoint=(0, 0),
degrees=180,
counterclockwise=False)
...
sketch2 = []
loop2_0 = Loop()
loop2_0.Line(endpoint=(0, 28))
loop2_0.Arc(endpoint=(0, 66),
degrees=180,
counterclockwise=False)
loop2_0.Line(endpoint=(0, 95))
loop2_0.Arc(endpoint=(0, 0),
degrees=180,
counterclockwise=True)
...

```

