


Acceleration X-Axis




I: Run-Up

II: Helical Ramp-In

III: Pocket Milling

Position X-Axis



Scenario 1

Scenario 2

Scenario 3

Scenario 4