






(a) Problem setting



(b) Optimal material distribution for compliance minimization



(c) Optimal material distribution for maximum stress minimization