


Workpiece Verification


Task Target

Analyze input 3D point clouds or images to identify workpieces that do not belong to the current batch.

Inputs




Mixed with external thread elbow



Front View Side View Top View

Different Model Number: M16



Mixed with model (12 to 8)



Front View Side View Top View

Different Workpiece: Wing Screw

Dialogue UI



Check whether the components in the image match their specifications. If any component is incorrect or mismatched, select the corresponding letter (A–D).




I will select option A as a example of the mismatch against the query specification. Answer: A

Structural Surface Inspection

Task Target

Identify manufacturing defects from workpiece point cloud or image data.

Inputs




Front View

Side View

Top View

Rivet Nut crack




Front View

Side View

Top View

Wing Nut deformation




Front View

Side View

Top View

Self-tapping Screw cut



Front View

Side View

Top View

Cup Head Screw dent

Dialogue UI



Analyze the given part:
Part 1: Is it normal? (Yes/No)
Part 2: If No, select the defect type:
A) Crack B) Cut C) Deformation D) Dent




Part 1: No
Part 2: B

Assembly Verification


Task Target

Analyze inputs to identify workpieces that fail to meet assembly specifications


Inputs




Hex Nut M14



Long screw



Extra Self tapping Screw



Front View

Side View

Top View

Extra Part:
Two Spring Washers

Dialogue UI



Check the image for any components that are incorrect, mismatched, or should not be present. If any issue is found, select the corresponding letter (A–F).



The metal screw a F is an extra component: four screws are present, but only three sets are required by the specification.