

$$s(k)$$



$$x_1(k) = h_1(k) * s(k)$$

$$s(k - \tau_2) = s(k)e^{-j\omega_c\tau_2}$$



$$x_2(k) = h_2(k) * s(k - \tau_2)$$

⋮

⋮

$$s(k - \tau_M) = s(k)e^{-j\omega_c\tau_M}$$



$$x_N(k) = h_M(k) * s(k - \tau_M)$$