



Scheduled Inspection Task

Q: Is there an early mechanical-seal degradation in the No. 3 trough-front oil pump for the last 3 months?

History Inspection Logs

[2026-01-10] Rear Bearing T at 57°C. Pressure slightly below.
...
[2026-01-17] Rear Bearing T at 59°C. Vibration increased rumble.

Technical Manuals

Maintenance Parameters

- Check belt loose, roller wear.
- Tension specification.
- Gear wear limits.
- Lubrication for bearings.
- ...

LLM


Reasoning

Evidences across cycles

Threshold



Vibration ,
Temperature
normal ranges.



~ 12% pressure
decline trend over 3
inspection records.

Output



Early-stage mechanical-seal
degradation risk.
[High Confidence: 75%]


Retrieving result

Query: No. 3 trough-front oil
pump Inspection;
Equipment: pump;
Fault: seal degrade ..

Record1: [2026-06-10]
Normal T, pressure 36.98;
Outcome: Oil level drop

Record2: [2026-05-17]
Pressure 39.65;
Outcome: Oil seepage

Record3: [2026-04-14]
rumble, pressure 42.24;
Outcome: Seal leakage



On-site Industrial Equipment
(e.g., Oil pump)

CHECK

Early-stage Seal
degradation risk.



Inspector checking

Sealing, Joints,
Oil level

Validation Result

Issue confirmed
Normal
Abnormal

Outcome Update

Visual Inspection

Measurement Tools
(Hermometer, Gage,
Other measurer)

Maintenance Check

Inspection
Record
Updated