




1. Substrate preparation




2. Resist patterning for circuit




3. Etching NbTiN




4. SiO₂ deposition




5. Resist patterning for spacers




6. Etching SiO₂




7. Resist patterning for junctions




8. Al evaporation




9. Al lift-off



10. New membrane chip



11. Al evaporation



12. Flip-chip assembly

