
Ground truth
Ours
Ours w/o online learning
LIO w/ online calibrated full linear model[22]
FAST-LIO-Multi-Sensor-Fusion [38]
FAST-LIO2 [35]
(a)
Y [m]
X [m]
Severe point cloud degeneration (Seq. 1)
(d)
sideview
Point cloud lacking geometric features
(e)
Large wheel slippage
(e.g., drifting)
Nonlinear motion for the kinematic model
(d - 1)
(d - 2)
(d - 3)
The narrow FOV LiDAR was used for imitating severe point cloud degeneration (e.g., tunnel).
Long-term point cloud degeneration areas where FAST-LIO2 failed in all sequences.
(b)
(3) Indoor stone tiles
(2) Outdoor
stone tiles
(1) Bricks
Point cloud degeneration and changing terrains (Seq. 2)
(c)
(2) Grass
(1) Concrete
Imagery ©2024 Airbus, Maxar,
Technologies, Map data ©2024
Point cloud degeneration and rough terrains (Seq. 3)